

Watershed Agricultural Program Guideline

1.1.05

LEVEL OF TREATMENT

The goal for Best Management Practices is to reduce the risk of pollutant loading to the greatest extent possible within limitations due to technical and economic feasibility.

Staff Guidelines

1. Limit agricultural runoff to surface waters and percolation to ground waters by using best available technology consistent with economically efficient farm and livestock management practices.
2. Economic or technical issues that limit the level of treatment should be well documented by the Whole Farm Planning Teams.